

**Table E-3-1**  
Well Construction Data Summary  
Pinewood Site  
Sumter County, SC

Well Identification	Screened Zone	Monitored Area	Installation Date	Easting	Northing	Ground Surface Elevation (ft amsl)	TOC Elevation (ft amsl)	Top of Screen Elevation (ft amsl)	Bottom of Screen Elevation (ft amsl)	Total Depth (ft below TOC)	Well Diameter (in)
CBC004	UBC-A	Other	8/31/1985	2143592.85	677158.31	99.59	103.17	14.59	4.59	98.58	2
MW005A	TLS	Section I	1/23/1987	2145610.52	674906.79	125.87	129.19	80.87	75.87	53.32	2
MW005BSR	SSDL	Section I	11/21/1995	2145622.43	674904.88	127.27	130.20	52.27	47.27	82.93	4
MW006TR	TLS	Section I	2/24/1994	2145535.99	675029.12	125.07	128.72	69.07	64.07	64.65	4
MW0075R	SSDL	Section I	1/18/1994	2145445.89	675147.90	125.08	128.65	50.08	45.08	83.57	4
MW008TR	TLS	Section I	2/10/1994	2145353.70	675270.92	124.25	128.17	68.25	58.25	69.92	4
MW009	SSDL	Section I	8/21/1985	2145262.00	675381.14	122.22	125.03	54.22	44.22	80.81	2
MW009A	TLS	Section I	2/4/1987	2145251.66	675397.52	122.62	126.04	67.62	62.62	63.42	2
MW010	SSDL	Section I	8/20/1985	2145166.69	675501.17	121.74	125.82	56.74	46.74	79.08	2
MW011	SSDL	Section I	8/24/1985	2145070.08	675618.03	122.35	126.65	57.35	47.35	79.30	2
MW012	SSDL	Section I	8/22/1985	2144978.16	675734.43	119.15	121.40	58.92	48.92	72.48	2
MW013	SSDL	Section I	8/12/1985	2144936.30	675844.47	116.82	119.66	60.82	50.82	68.84	2
MW014	SSDL	Section I	8/6/1985	2145068.60	675946.67	117.98	121.74	57.98	47.98	73.76	2
MW015	SSDL	Section I	8/7/1985	2145183.68	676048.95	119.08	123.01	61.08	51.08	71.93	2
MW016TR	TLS	Section I	3/10/1994	2145301.88	676154.57	118.37	122.13	74.37	69.37	52.76	4
MW017	SSDL	Section I	8/9/1985	2145417.47	676237.42	117.68	120.75	58.68	48.68	72.07	2
MW018APR	PSDL	Section II	6/27/1994	2144748.46	676444.80	127.04	130.87	41.04	31.04	99.83	4
MW018B	SSDL	Section II	Unknown	2144752.99	676450.95	126.96	130.40	64.96	54.96	75.44	2
MW019A	TLS	Section II	Unknown	2144596.89	676426.19	125.85	129.82	72.85	67.85	61.97	4
MW020A	TLS	Section II	Unknown	2144445.94	676423.15	126.68	130.63	76.68	71.68	58.95	4
MW020B	SSDL	Section II	Unknown	2144460.92	676429.12	126.70	130.46	65.70	50.70	79.76	4
MW021	SSDL	Section II	8/30/1985	2144303.40	676467.93	126.01	131.98	72.01	62.01	69.97	2
MW022TR	TLS	Section II	3/9/1994	2144152.72	676491.21	129.50	133.28	75.50	70.50	62.78	4
MW023ATR	TLS	Section II	3/8/1994	2144031.90	676576.98	128.68	132.28	80.68	75.68	56.60	4
MW023SR	SSDL	Section II	3/30/1994	2144025.47	676581.66	128.87	132.28	65.87	55.87	76.41	4
MW024TR	TLS	Section II	3/1/1994	2143940.97	676824.16	131.57	135.27	82.57	77.57	57.70	4
MW025SR	SSDL	Section II	3/29/1994	2143940.73	676832.16	132.82	135.58	63.82	58.82	76.76	4
MW026ATR	TLS	Section II	3/4/1994	2143971.99	676980.66	131.83	135.52	85.83	80.83	54.69	4
MW026B	SSDL	Section II	7/89	2143964.60	676978.12	132.05	135.64	76.05	56.05	79.59	4
MW027A	SSDL	Section II	2/3/1987	2143992.13	677140.14	132.39	135.02	75.29	70.29	64.73	2
MW027AR	SSDL	Section II	3/22/2001	2143995.49	677113.05	132.52	136.23	Unknown	61.02	75.21	4
MW027BTR	TLS	Section II	2/24/1994	2144003.88	677112.53	132.22	135.69	85.22	80.22	55.47	4
MW028A	TLS	Section II	7/13/1989	2144051.65	677249.61	132.70	136.30	88.70	83.70	52.60	4
MW028B	SSDL	Section II	7/13/1989	2144047.36	677268.84	132.70	136.32	74.70	64.70	71.62	4
MW029	TLS	Section II	10/24/1986	2144076.11	677418.44	133.27	136.48	89.27	84.27	52.21	2
MW030	TLS	Section II	10/22/1986	2144108.96	677563.65	135.00	138.17	87.50	82.50	55.67	2
MW031TR	TLS	Section I	4/18/1996	2145623.99	676239.96	117.86	121.43	65.86	60.86	60.57	4
MW033	TLS	Section I	8/11/1987	2145921.53	675825.40	125.75	129.06	67.25	62.25	66.81	2
MW034	TLS	Other	8/13/1987	2146185.29	675657.13	137.43	140.50	68.43	63.43	77.07	2
MW035S	SSDL	Section I	Unknown	2145729.75	676118.25	126.00	130.74	48.00	43.00	87.74	4
MW036SR	SSDL	Section I	4/6/1994	2145913.91	675838.09	126.54	129.96	49.54	44.54	85.44	4
MW0375R	SSDL	Section I	4/4/1994	2146074.03	675608.58	126.92	130.99	47.92	42.92	88.07	4
MW0385R	SSDL	Section I	6/29/1994	2146283.47	675387.79	129.53	133.19	49.53	44.53	88.66	4
MW039P	PSDL	Section I	1/90	2145597.00	674921.10	125.47	129.07	39.47	29.47	99.60	4
MW040P	PSDL	Section I	Unknown	2145171.90	675486.56	122.08	125.29	34.08	29.08	96.21	4
MW041T	TLS	Section I	1/18/1991	2145178.05	675493.91	122.63	125.99	69.63	59.63	66.36	4
MW042TR	TLS	Section I	3/15/1996	2145086.18	675609.78	123.35	126.29	69.35	64.35	61.94	4
MW043T	TLS	Section I	1/3/1991	2144973.69	675756.85	119.36	122.63	77.36	72.36	50.27	4
MW044P	PSDL	Section I	1/90	2144974.55	675744.77	119.89	122.45	37.89	32.89	89.56	4
MW045T	TLS	Section I	1/3/1991	2145089.08	675963.58	119.55	122.84	75.55	70.55	52.29	4
MW046P	PSDL	Section I	2/21/1990	2145077.06	675954.90	119.06	122.64	32.06	27.06	95.58	4
MW047P	PSDL	Section I	1/90	2145286.51	676132.32	119.37	121.89	47.37	37.37	84.52	4
MW048TR	TLS	Section II	3/20/1996	2145330.85	676732.14	135.23	138.73	75.23	70.23	68.50	4
MW049T	TLS	Section II	5/1/1991	2145180.26	676647.39	128.44	131.95	68.44	63.44	68.51	4
MW050T	TLS	Section II	3/26/1991	2145032.25	676601.71	126.80	129.92	73.80	68.80	61.12	4
MW051T	TLS	Section II	3/26/1991	2144907.33	676488.09	127.68	131.21	76.68	71.68	59.53	4
MW052T	TLS	Section II	3/26/1991	2144290.61	676448.73	128.81	131.35	78.81	73.81	57.54	4
MW053P	PSDL	Section II	4/27/1990	2144155.73	676501.74	128.47	133.15	42.47	32.47	100.68	4
MW054T	TLS	Section II	3/26/1991	2143922.25	676688.93	130.02	133.65	81.02	76.02	57.63	4
MW055P	PSDL	Section II	6/27/1990	2143919.17	676674.64	130.47	133.79	50.47	40.47	93.32	4
MW056P	PSDL	Section II	6/27/1990	2143968.19	676961.74	132.02	135.42	52.02	42.02	93.40	4
MW057S	SSDL	Section II	4/25/1991	2144081.80	677429.54	134.09	137.32	76.09	66.09	71.23	4
MW058P	PSDL	Section II	6/27/1990	2144114.56	677580.64	136.28	140.07	51.28	41.28	98.79	4
MW059S	SSDL	Section II	4/30/1991	2144142.71	677701.83	137.64	141.25	68.64	58.64	82.61	4
MW060SR	SSDL	Section II	11/15/1995	2144182.44	677862.25	141.77	145.13	61.77	56.77	88.36	4
MW061T	TLS	Section II	3/26/1991	2144144.11	677713.34	137.72	141.12	82.72	77.72	63.40	4
MW062S	SSDL	Section II	6/19/1990	2145414.55	677813.48	154.49	157.99	64.49	59.49	98.50	4
MW063SR	SSDL	Section II	5/16/1996	2145699.33	677788.45	158.97	162.42	45.97	40.97	121.45	4
MW064P	PSDL	Section II	11/10/1992	2145310.26	676708.03	134.80	138.45	35.80	25.80	112.65	4
MW071T	TLS	Section I	10/5/1992	2145736.20	676139.81	126.90	130.44	56.90	51.90	78.54	4
MW072PR	PSDL	Section I	2/16/2016	2145875.38	676010.91	127.97	130.41	29.53	24.53	103.44	2
MW073T	TLS	Section I	12/14/1992	2145866.75	676002.97	124.69	130.65	61.69	56.69	73.96	4
MW077P	PSDL	Other	12/16/1992	2146469.18	675823.70	142.40	146.11	30.40	25.40	120.71	4
MW078T	TLS	Other	12/16/1992	2146459.95	675832.24	142.10	145.79	58.10	53.10	92.69	4
MW080TR	TLS	Section II	4/15/1996	2145710.07	677785.27	158.97	162.38	58.97	53.97	108.41	4
MW0865R	SSDL	Section II & III	5/29/1996	2145735.94	677318.34	162.92	166.54	54.92	49.92	116.62	4
MW087P	PSDL	Section II & III	9/28/1992	2145739.92	677306.97	154.89	166.81	47.31	37.31	129.50	4
MW089T	TLS	Section II & III	12/20/1992	2145785.60	677622.50	156.70	160.20	55.99	50.99	109.21	4
MW0905R	SSDL	Section II & III	12/21/1995	2145777.69	677619.28	156.26	160.10	49.10	44.10	116.00	4
MW091PR	PSDL	Section II & III	1/12/1996	2145775.77	677609.87	156.41	160.19	34.41	29.41	130.78	4

**Table E-3-1**  
Well Construction Data Summary  
Pinewood Site  
Sumter County, SC

Well Identification	Screened Zone	Monitored Area	Installation Date	Easting	Northing	Ground Surface Elevation (ft amsl)	TOC Elevation (ft amsl)	Top of Screen Elevation (ft amsl)	Bottom of Screen Elevation (ft amsl)	Total Depth (ft below TOC)	Well Diameter (in)
MW0925R	SSDL	Other	2/3/1995	2148000.32	676819.91	174.17	177.58	28.17	23.17	154.41	4
MW093PR	PSDL	Other	1/27/1995	2148003.88	676809.11	173.43	177.27	17.43	12.43	164.84	4
MW094PR	PSDL	Other	1/24/1995	2147312.57	677584.03	174.47	177.81	14.47	9.47	168.34	4
MW095P	PSDL	Other	10/30/1992	2148081.33	676175.54	172.20	175.35	22.20	17.20	158.15	4
MW096T	TLS	Other	1/8/1993	2148083.48	676190.42	171.51	175.78	42.51	37.51	138.27	4
MW097T	TLS	Other	12/16/1992	2147236.21	675532.78	158.10	161.82	23.10	13.10	148.72	4
MW098TR	TLS	Other	2/8/1995	2147997.25	676829.99	174.17	177.65	43.17	38.17	139.48	4
MW099P	PSDL	Section II & III	12/19/1992	2145670.81	677018.09	150.60	154.27	43.60	33.60	120.67	4
MW100P	PSDL	Section II	7/25/1994	2144169.58	677848.11	140.47	144.72	52.47	47.47	97.25	4
MW101T	TLS	Section III	6/22/1995	2146580.31	676683.31	164.46	167.96	57.46	47.46	120.50	4
MW102S	SSDL	Section III	6/23/1995	2146573.55	676674.81	164.22	167.72	42.22	37.22	130.50	4
MW103P	PSDL	Section III	6/27/1995	2146572.88	676666.69	163.92	167.42	31.92	26.92	140.50	4
MW114T	TLS	Section III	7/30/1996	2146704.50	676814.00	165.33	168.76	33.33	23.33	145.43	4
MW115T	TLS	Section III	7/26/1996	2146711.97	676821.21	165.41	168.84	17.41	12.41	156.43	4
MW116T	TLS	Section III	8/3/1996	2146842.07	676955.27	165.38	168.72	25.88	20.88	147.84	4
MW117T	TLS	Section III	8/12/1996	2146849.81	676961.65	165.40	168.71	15.40	10.40	158.31	4
MW125P	PSDL	Section III	5/1/2001	2145728.24	676748.97	130.93	134.41	Unknown	20.99	113.42	4
MW126T	TLS	Other	2/21/1995	2147328.09	677574.14	174.15	177.15	41.15	36.15	141.00	4
MW127T	TLS	Section II	6/30/1995	2144765.56	676447.37	126.73	129.83	76.73	71.73	58.10	4
MW128S	SSDL	Section II	7/1/1995	2145039.15	676565.58	125.97	129.58	53.97	48.97	80.61	4
MW129S	SSDL	Section II	7/3/1995	2145178.51	676637.69	127.44	130.85	54.44	49.44	81.41	4
MW131T	TLS	Section I	3/26/2001	2146004.50	675730.74	124.94	128.62	Unknown	58.94	69.68	4
MW132T	TLS	Section I	4/9/2001	2146093.85	675582.50	124.96	128.54	Unknown	60.96	67.58	4
MW133T	TLS	Section I	4/9/2001	2146207.57	675472.84	127.13	130.58	Unknown	58.13	72.45	4
MW134T	TLS	Section I	4/4/2001	2146270.52	675401.77	129.52	132.94	Unknown	55.52	77.42	4
MW135S	SSDL	Section III	5/2/2001	2145720.21	676756.23	130.43	133.73	Unknown	42.73	91.00	4
MW137T	TLS	Section III	8/1/2011	2146751.47	677660.77	154.63	157.63	38.63	28.63	129.00	2
MW138P	PSDL	Section III	8/1/2011	2146744.82	677661.89	154.87	157.81	12.87	7.87	149.94	2
MW139S	SSDL	Section III	7/30/2011	2147041.82	677389.85	160.37	163.43	35.37	30.37	133.06	2
MW140S	SSDL	Other	7/27/2011	2148077.05	676191.09	172.75	175.88	30.75	25.75	150.13	2
MW141T	TLS	Other	7/29/2011	2147616.49	675961.84	155.51	158.54	37.51	32.51	126.03	2
MW142T	TLS	Section II	1/8/2015	2145348.40	677811.23	151.62	154.65	73.62	63.62	91.03	2
MW143T	TLS	Section II	1/9/2015	2145013.69	677845.92	146.16	148.54	81.16	71.16	77.38	2
MW144T	TLS	Section III	1/5/2015	2147039.63	677418.99	160.03	162.57	44.03	39.03	123.54	2
MW145P	PSDL	Section I	12/22/2014	2146562.18	676201.27	120.56	123.66	28.16	23.06	100.50	2
MW146P	PSDL	Section I	12/18/2014	2146087.42	675609.86	125.39	127.96	28.99	23.99	104.07	2
MW147P	PSDL	Section I	12/15/2014	2146297.06	675369.41	130.79	133.53	28.79	23.79	109.74	2
MW148P	PSDL	Section III	12/19/2014	2147050.09	677377.89	159.94	162.43	9.94	4.94	157.49	2
MW149P	PSDL	Section III	1/8/2015	2147067.84	677168.77	164.50	167.23	33.00	28.00	139.23	2
OC002	OC	Other	1/23/1987	2145307.76	676558.90	119.97	123.47	79.97	74.97	48.50	2
OC003	OC	Section I	1/26/1989	2144973.46	675861.77	116.87	120.93	85.87	80.87	40.06	2
OC004	OC	Section I	1/28/1987	2145379.39	675178.01	122.38	126.38	82.38	77.38	49.00	2
OC005	OC	Section I	6/10/1994	2145490.27	675083.09	125.05	128.70	100.05	95.05	33.65	2
OC006	OC	Section I	6/10/1994	2145487.13	675087.97	125.11	128.48	84.11	79.11	49.37	2
OC007	OC	Section II	6/10/1994	2144128.22	677630.67	136.98	140.56	105.98	100.98	39.58	2
OC008	OC	Section II	1/14/2015	2146102.24	676152.18	137.09	140.74	96.09	91.09	49.65	2
OC009	OC	Section I	1/13/2003	2145538.45	675013.60	125.15	128.04	95.15	85.15	42.89	2
OC010	OC	Section I	1/13/2003	2145345.18	675281.63	124.28	127.07	88.28	78.28	48.79	2
OC011	OC	Section I	1/14/2003	2145149.80	675520.35	121.75	124.70	86.75	76.75	47.95	2
OC012	OC	Section I	1/14/2003	2145202.32	676068.06	119.16	122.16	93.66	83.66	38.50	2
OC013	OC	Section I	1/14/2003	2145437.88	676255.84	117.00	119.78	92.00	82.00	37.78	2
OC014	OC	Section I	1/14/2003	2145768.28	676099.64	127.93	130.60	82.93	72.93	57.67	2
OC015	OC	Section I	1/14/2003	2145936.87	675818.58	125.95	128.77	88.45	78.45	50.32	2
OC016	OC	Section I	1/15/2003	2146183.01	675496.33	126.98	129.86	91.98	81.98	47.88	2
OC5001	OC	Section III	7/20/2005	2146708.70	676757.60	155.95	158.94	105.95	95.95	62.99	2
OC5002	OC	SWMU Area	7/17/2005	2146512.10	676539.50	149.64	152.45	105.64	95.64	56.81	2
OC5003A	OC	SWMU Area	7/12/2005	2146923.80	676444.30	144.49	147.47	102.49	92.49	54.98	2
OC5003B	OC	SWMU Area	7/20/2005	2146922.20	676430.40	144.49	147.82	119.49	114.49	33.33	2
OC5004	OC	SWMU Area	7/17/2005	2146886.90	676012.60	140.84	143.72	115.84	105.84	37.88	2
OC5005	OC	SWMU Area	7/14/2005	2146321.70	676378.20	151.69	154.66	111.69	101.69	52.97	2
OC5006A	OC	SWMU Area	7/10/2005	2146470.60	676111.00	136.48	139.07	103.45	98.48	40.59	2
OC5006B	OC	SWMU Area	7/11/2005	2146079.00	676172.40	136.48	139.78	116.48	106.48	33.30	2
OC5008R	OC	SWMU Area	1/14/2015	2146102.24	676152.18	156.16	158.95	111.16	101.16	57.79	2
OC5011	OC	SWMU Area	7/16/2005	2145478.40	675822.50	126.21	129.34	116.21	111.21	18.13	2
P042B	UBC-A	Other	10/16/1992	2146843.73	676621.06	152.70	156.24	-0.30	-5.30	161.54	4
P042T	TLS	Other	10/20/1992	2146848.18	676607.96	152.70	156.19	14.70	4.70	151.49	4
P112A	TLS-Channel	Section III	12/10/1993	2146416.78	677692.79	151.26	154.45	24.26	19.26	135.19	2
P112B	TLS-Channel	Section III	12/9/1993	2146406.47	677694.36	151.35	154.57	15.35	10.35	144.22	2
P112C	TLS-Channel	Section III	12/9/1993	2146396.15	677696.62	151.43	154.58	-2.57	-7.57	162.15	2
P112D	TLS-Channel	Section III	12/8/1993	2146385.93	677698.94	151.39	154.54	-14.61	-19.61	174.15	2
P114A	TLS-Channel	Other	12/17/1993	2147041.63	676538.83	145.90	149.17	29.90	25.90	123.27	2
P114B	TLS-Channel	Other	12/17/1993	2147050.77	676532.02	144.86	148.28	13.86	9.86	138.42	2
P114C	TLS-Channel	Other	12/16/1993	2147057.66	676526.40	144.25	147.75	-6.75	-11.75	159.50	2
P114D	TLS-Channel	Other	12/15/1993	2147067.69	676520.47	143.62	147.16	-20.38	-24.38	171.99	2
PBC002	UBC-A	Section I	3/12/1985	2145209.70	675139.10	146.95	149.40	15.95	13.95	135.45	2
PBC004	UBC-A	Section II	3/18/1985	2144304.42	676448.26	126.75	131.47	26.75	22.75	108.72	2
PBC006	UBC-A	Other	4/9/1985	2144015.31	676361.21	107.44	110.71	31.44	27.44	83.27	2
PSDL001	TLS	Section III	4/4/1985	2146096.12	677745.34	153.79	156.93	45.79	40.79	116.14	2
PSDL004	SSDL	Other	4/8/1985	2143578.40	677172.76	99.29	102.58	70.29	66.29	36.29	2
PSDL005	TLS	Other	5/2/1985	2144032.62	676360.21	107.86	111.14	79.86	74.86	36.28	2

**Table E-3-1**  
Well Construction Data Summary  
Pinewood Site  
Sumter County, SC

Well Identification	Screened Zone	Monitored Area	Installation Date	Easting	Northing	Ground Surface Elevation (ft amsl)	TOC Elevation (ft amsl)	Top of Screen Elevation (ft amsl)	Bottom of Screen Elevation (ft amsl)	Total Depth (ft below TOC)	Well Diameter (in)
PSDL007	SSDL	Other	4/10/1985	2144600.41	676088.73	101.80	106.13	58.80	54.80	51.33	2
PSDL012	TLS	Other	4/18/1985	2144461.65	675878.30	102.65	106.08	78.65	73.65	32.43	2
PSDL013	PSDL	Other	4/22/1985	2144417.20	675396.63	129.36	143.53	41.36	36.36	107.17	2
PSDL014	TLS	Other	4/22/1985	2144939.80	675395.46	139.47	142.60	73.47	68.47	74.13	2
PSDL014A	SSDL	Other	4/22/1985	2144934.61	675408.44	139.46	142.78	49.46	44.46	98.32	2
PSDL017	TLS	Section I	4/25/1985	2146236.75	675042.84	154.54	158.16	65.54	61.54	96.62	2
PSDL017A	SSDL	Section I	4/25/1985	2146218.63	675030.37	154.54	157.64	49.54	44.54	113.10	2
PSDL021	TLS	Section I	5/2/1985	2145371.30	675165.35	121.72	125.39	65.72	61.72	63.67	2
PSDL021A	SSDL	Section I	Unknown	2145366.26	675186.96	121.67	124.50	48.67	43.67	80.83	2
SL001	TLS	Section I	8/22/1986	2144949.10	675848.81	116.97	120.29	76.97	71.97	48.32	2
SL002	TLS	Section I	8/21/1986	2145175.72	676042.77	120.00	123.50	74.00	69.00	54.50	2
SL003	TLS	Section I	8/20/1986	2145426.97	676245.56	117.65	121.14	72.65	67.65	53.49	2
SL004	TLS	Other	10/1/1986	2144921.35	676060.75	103.40	106.75	70.40	65.40	41.35	2
SL005	PSDL	Other	10/2/1986	2144933.15	676056.70	66.74	107.11	45.14	40.14	66.97	2
SL006	TLS	Other	10/2/1986	2145310.19	676546.94	119.55	122.82	73.55	68.55	54.27	2
SL007	SSDL	Other	10/2/1986	2145321.47	676555.85	119.80	123.66	53.80	48.80	74.86	2
SL013	PSDL	Section I	1/26/1988	2145388.86	676159.40	122.47	125.98	37.47	32.47	93.51	4
SL014PR	PSDL	Section I	6/23/1994	2145361.80	675262.54	124.46	127.98	34.16	26.46	101.52	4
SL015	PSDL	Section I	2/22/1988	2146205.55	675021.52	154.35	158.31	31.35	26.35	131.96	4
SL016	PSDL	Section I	2/25/1988	2145913.72	675835.36	125.77	129.61	35.77	30.77	98.84	4
SL019SR	SSDL	Section II & III	12/5/1995	2145676.52	677037.01	152.15	155.65	30.15	25.15	130.50	4
SL020SR	SSDL	Section II	7/21/1994	2144846.88	677891.30	149.31	152.96	55.31	50.31	102.65	4
SL021PR	PSDL	Section II	7/7/1994	2144852.82	677890.42	148.93	152.63	45.93	40.93	111.70	4
SL022	PSDL	Section II	1/22/1988	2144028.94	677259.28	132.55	135.22	49.19	44.19	91.03	4
SL023	PSDL	Section II	2/11/1988	2144283.21	676457.69	128.03	131.33	41.03	36.03	95.30	4
SL024	PSDL	Section II	2/8/1988	2144461.41	676415.80	127.06	130.87	43.87	38.87	92.00	2
UBC001	UBC-B	Other	8/8/1986	2144932.47	676068.63	103.58	106.44	11.58	1.58	104.86	2
UBC004	UBC-A	Other	8/3/1986	2145326.58	676539.63	119.84	123.11	26.84	16.84	106.27	2
UBC005	UBC-B	Other	10/1/1986	2144583.91	676092.26	103.53	107.49	9.53	-0.47	107.96	2
UBC006	UBC-B	Section I	9/30/1986	2145192.14	676058.63	119.78	123.64	4.78	-5.22	128.86	2
UBC008	UBC-B	Section I	11/13/1986	2144965.50	675852.82	117.32	120.79	7.32	-2.68	123.47	2
UBC010	UBC-A	Section I	1/31/1991	2145526.45	675019.82	124.59	127.72	23.59	13.59	114.13	4
UBC011	UBC-A	Section I	5/20/1991	2145159.85	675510.49	122.19	125.60	19.19	14.19	111.41	4
UBC012	UBC-A	Section I	5/24/1991	2144986.26	675749.63	120.25	123.67	30.25	25.25	98.42	4
UBC013	UBC-A	Section I	5/13/1991	2145097.12	675972.37	119.45	122.87	21.45	16.45	106.42	4
UBC014	UBC-A	Section I	5/13/1991	2145309.20	676153.15	119.15	122.73	34.15	24.15	98.58	4
UBC015AR	UBC-A	Section II	5/10/1996	2144888.88	676480.75	127.41	130.58	35.41	30.41	100.17	4
UBC016	UBC-A	Section II	3/11/1992	2144589.44	676418.78	126.75	130.07	30.75	25.75	104.32	4
UBC017	UBC-A	Section II	3/8/1995	2144020.04	676587.69	129.67	132.29	25.67	21.67	110.62	4
UBC017B	UBC-B	Section II	3/11/1991	2143920.84	676664.63	130.55	134.24	9.55	4.55	129.69	4
UBC018	UBC-A	Section II	3/2/1995	2143941.36	676841.49	132.07	135.49	32.07	27.07	108.42	4
UBC018B	UBC-B	Section II	12/8/1991	2143971.86	676987.12	132.19	135.58	14.19	9.19	126.39	4
UBC019	UBC-A	Section I	12/9/1992	2145755.85	676107.77	125.30	131.77	15.30	5.30	126.19	4
UBC021	UBC-A	Other	12/11/1992	2146478.22	675814.99	142.60	146.14	10.60	0.60	145.54	4
UBC022AR	UBC-A	Section II	11/30/1995	2145170.83	676632.88	127.54	130.82	19.54	14.54	116.28	4
UBC024	UBC-A	Section II & III	9/31/1992	2145737.24	677290.04	163.70	167.20	29.70	24.70	142.50	4
UBC025	UBC-A	Other	11/10/1992	2147318.91	677569.43	174.40	178.24	4.90	-0.10	178.34	4
UBC026	UBC-A	Section II & III	10/5/1992	2145787.30	677583.70	157.17	160.67	30.17	25.17	135.50	4
UBC027	UBC-A	Other	10/23/1992	2148015.08	676802.14	173.90	177.30	1.90	-3.10	180.40	4
UBC028AR	UBC-A	Other	2/14/1995	2148088.34	676168.88	171.44	175.03	9.44	4.44	170.59	4
UBC029AR	UBC-A	Section II & III	12/11/1995	2145665.03	676998.62	151.10	154.60	13.10	8.10	146.50	4
UBC030	UBC-A	Section II	7/27/1994	2144081.41	677431.10	133.72	137.52	29.72	24.72	112.80	4
UBC031	UBC-A	Section III	6/27/1995	2146567.96	676657.39	163.60	167.10	13.60	8.60	158.50	4
UBC034	UBC-A	Section III	4/27/2001	2146057.30	676620.18	131.33	134.76	13.17	8.17	126.59	4
UBC048	UBC-A	Section III	8/8/1996	2146711.98	676828.60	165.37	168.86	7.37	2.37	166.49	4
UBC049	UBC-A	Section III	8/14/1996	2146857.21	676968.34	165.43	168.54	4.43	-0.57	169.11	4
UBC051	UBC-A	Section II	7/2/1995	2144009.13	677126.78	132.80	135.59	30.80	25.80	109.79	4
UBC052	UBC-A	Section II	7/1/1995	2144148.01	677721.65	137.79	140.95	24.95	19.95	121.36	4
UBC053	UBC-A	Section I	4/20/2001	2145355.84	675278.40	124.97	128.25	16.97	11.97	116.28	4
UBC054	UBC-A	Section III	7/31/2011	2146739.54	677662.61	155.02	157.99	5.02	0.02	157.97	2
UBC055	UBC-A	Other	7/28/2011	2147621.35	675966.24	155.56	158.61	19.56	14.56	144.05	2
UBC056	UBC-A	Other	7/28/2011	2147264.35	675477.52	161.15	164.09	18.15	13.15	150.94	2
UBC057	UBC-A	Section II	1/6/2015	2144733.53	677878.41	141.34	144.17	21.34	16.34	127.84	2
UBC058	UBC-A	Section II	1/7/2015	2145367.95	677812.69	151.72	154.66	33.72	28.72	125.94	2
UBC059	UBC-A	Section I	12/18/2014	2145889.95	675824.07	128.15	130.61	16.15	11.15	119.46	2
UBC060	UBC-A	Section I	12/17/2014	2146166.11	675503.76	127.60	130.30	10.60	5.60	124.70	2
UBC061	UBC-A	Section III	12/18/2014	2147048.18	677383.77	159.82	162.57	-1.18	-6.18	168.75	2
UBC062	UBC-A	Section II	1/8/2015	2145021.48	677844.82	146.03	148.57	22.03	17.03	131.54	2
UBC063	UBC-A	Section III	1/7/2015	2147068.54	677160.07	164.47	167.10	7.47	2.47	164.63	2
WT008	WT	SWMU Area	12/13/1986	2146866.84	676703.90	153.45	156.71	135.45	130.45	26.26	2
WT010	WT	Other	Unknown	2144238.05	675780.12	104.71	107.96	86.21	81.21	26.75	2
WT011	WT	Other	Unknown	2143778.54	675850.11	97.89	101.21	82.89	77.89	23.32	2
WT012	WT	Other	Unknown	2143775.60	675906.65	96.93	100.27	83.93	78.93	21.34	2
WT015	WT	Other	Unknown	2144333.36	676190.45	107.26	110.57	Unknown	89.26	21.31	2
WT016	WT	Other	Unknown	2145589.86	676100.78	102.53	105.90	94.03	89.03	16.87	2
WT026	WT	SWMU Area	6/9/1989	2146447.77	676231.08	137.93	140.07	132.93	122.93	17.14	4
WT027	WT	Section I	3/20/1990	2145628.22	676215.65	119.06	122.06	112.06	107.06	15.00	4
WT030	WT	Other	6/5/1990	2144876.52	676046.13	102.95	106.05	97.45	92.45	13.60	4
WT032	WT	SWMU Area	6/6/1990	2146107.08	675828.25	137.69	140.81	119.69	114.69	26.12	4
WT033	WT	Other	10/5/2010	2147664.93	677392.02	174.90	178.13	149.90	139.90	38.23	2

**Table E-3-1**  
Well Construction Data Summary  
Pinewood Site  
Sumter County, SC

Well Identification	Screened Zone	Monitored Area	Installation Date	Easting	Northing	Ground Surface Elevation (ft amsl)	TOC Elevation (ft amsl)	Top of Screen Elevation (ft amsl)	Bottom of Screen Elevation (ft amsl)	Total Depth (ft below TOC)	Well Diameter (in)
WT034	WT	Section III	10/5/2010	2147173.26	677208.72	156.17	159.27	146.17	136.17	23.10	2
WT035	WT	Section III	10/5/2010	2147060.42	677012.18	151.82	155.09	142.32	132.32	22.77	2
WT036	WT	SWMU Area	10/6/2010	2146694.05	676677.53	157.20	160.03	142.20	132.20	27.83	2
WT037	WT	SWMU Area	10/6/2010	2146999.15	676698.82	149.24	152.30	139.24	129.24	23.06	2
WT038	WT	SWMU Area	10/6/2010	2146729.78	676397.22	145.57	148.60	136.07	126.07	22.53	2
WT039	WT	SWMU Area	10/5/2010	2146896.46	676008.73	140.43	143.37	134.93	124.93	18.44	2
WT040	WT	SWMU Area	10/5/2010	2146490.35	675691.03	144.55	147.67	132.55	122.55	25.12	2
WT041	WT	Section II	12/9/2014	2144089.73	677467.95	134.30	137.22	124.30	109.30	27.92	2
WT042	WT	Section II	12/8/2014	2143999.12	677087.91	132.79	135.68	125.79	115.79	19.89	2
WT043	WT	Section II	12/5/2014	2144311.52	676437.68	128.65	131.68	121.15	111.15	20.53	2
WT044	WT	Section II	12/5/2014	2144788.19	676452.72	126.97	130.00	121.47	111.47	18.53	2
WT045	WT	Section I	12/4/2014	2145279.55	676165.77	119.33	122.37	112.33	102.33	20.04	2
WT046	WT	Section I	12/4/2014	2145047.32	675931.26	118.51	121.79	113.51	103.51	18.28	2
WT047	WT	Section I	12/4/2014	2145105.11	675577.07	122.54	125.87	117.54	107.54	18.33	2
WT048	WT	Section I	12/4/2014	2145493.62	675078.62	125.04	127.75	120.04	110.04	17.71	2
WT049	WT	Section I	12/8/2014	2143912.07	676716.78	130.55	133.70	126.50	119.05	29.66	2

**Notes:**

- ft = Feet
- in = Inches
- TOC = Top of Casing
- hrs = hours
- bgs = Below ground surface
- amsl = Above mean sea level